

VISUAL TANK INSPECTION REPORT

	ETT-112 Hercules Shipyard / Freeport, Anolon	Texas	Your Reference: Our Reference: FP/97-5136 Date: March 6, 1997
Tank			
Number	1C	2C	3C
Tank Coating	Mild Steel	Mild Steel	Mild_Steel
Last			
Cargo	99.9% Cyclohexane	99.9% Cyclohexa	ne 99.9% Cyclohexane
Second Last Cargo			
Third Last			
Cargo			
Visual Cleanliness Accepted *	Accepted	Accepted	Accepted
/isual Cleanliness Rejected *			
ime/Date	1410	1410	1410
Inspected	03/06/97	03/06/97	03/06/97
Method said to hav	e been used to clean tanks: _1	Tanks #1 Center,	#2 Center, #3 Center and Lines: Stripped and Blown.

Information regarding previous cargoes, tank coating and cleaning method was obtained from vessel personnel and cannot be guaranteed as accurate by Caleb Brett U.S.A., Inc. and no liability can be assumed for errors resulting from improper information supplied. This report, of necessity, is based on such information.

* The cleanliness of inspected tank(s) is/are based on visual inspection of tank surfaces and line system at accessible areas only. This document does not cover the cleanliness of tank surfaces and line system at inaccessible spots and/or possible release of components of previous cargoes during loading, discharge or transport of the cargo in question, for which the vessel is fully responsible. Suitability of tank coating for intended cargo must be guaranteed by vessel's owner or by suppliers of the coating.

T S-Caleb Brott